



Concorde Battery Corporation
 2009 San Bernardino Road
 West Covina, CA 91790
 Phone (800) 757-0303 or (626) 813-1234
 Fax (800) 237-4209 or (626) 813-1235
<http://www.concordebattery.com>

An ISO 9001:2000 + AS9100B Certified Company

Eligibility List

Revision: EL-65 (Revised: 10/3/2011)

(Contact Concorde factory or consult website for latest revision number)

FAA Approval Information

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Aerofab Inc.	(See Revo Inc.)				
Agusta	A109C, A109E, A119, AW119 MKII (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SR09360RC	RG-407	FAA-PMA Supplement No. 57, dd 06/16/03 and FAA TSO-C173 (Amendment to STC to add AW119 MK II on 01/15/10)
Agusta	A109A, A109C, A109E (To replace nickel-cadmium battery – Contact Rotorcraft Support for replacement details prior to battery purchase)	Rotorcraft Support (818) 997-7667	STC# SR01456LA	RG-407	FAA-PMA Supplement No. 62, dd 10/30/03 and FAA TSO-C173
Alon	(See Univair)				
American Champion	7ECA, 7GCAA, 7KCAB	American Champion (800) 223-9381 (262) 534-6315	TC# A-759	RG-25	FAA-PMA Supplement No. 31, dd 06/03/97
American Champion	8GCBC, 8KCAB	American Champion (800) 223-9381 (262) 534-6315	TC# A-21CE	RG-25	FAA-PMA Supplement No. 31, dd 06/03/97
Aviat Inc. / Sky International	Aviat Model A-1A, A-1B Aviat Pitts Model S-2C	Aviat Inc. / Sky International (307) 885-3151	TC# A22NM & A8SO	RG-25	FAA-PMA Supplement No. 42, dd 08/06/01
Aviat Inc. / Sky International	Aviat Model A-1 Aviat Pitts Models S-1S, S-1T, S-2, S-2A, S-2S, S-2B	Aviat Inc. / Sky International (307) 885-3151	TC# A22NM & A8SO	RG-25	FAA-PMA Supplement No. 18, dd 08/02/95
Avions de Transport Regional (ATR)	ATR42 Series; ATR72 Series (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST03930AT (Kit)	RG-380E/44 (Main) RG-42 (Emergency) 7945 (Dummy temp. sensor); 6716 Placard	FAA-PMA Supplement No. 97, dd 09/28/11 & P/N RG-380E/44 and RG-42 are FAA TSO-C173 authorized
B-N Group Ltd.	BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27, BN-2T, BN-2T-4R	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390E	FAA-PMA Supplement No. 34, dd 11/18/97 and FAA TSO-C173
Beech	(See Hawker Beechcraft)				
Bell	206A & 206B (To replace nickel-cadmium battery – Contact Adv. Pwr. For replacement details prior to battery purchase)	Advanced Power (877) 522-8837 (626) 969-7227	STC# SR00318SE	RG-206	FAA-PMA Supplement No. 26, dd 06/21/96 and FAA TSO-C173
Bell	206A & 206B (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC & STA# SR09054RC	RG-206	FAA-PMA Supplement No. 23, dd 04/04/96 and FAA TSO-C173
Bell	204B, 205B, 205A-1, 212, 412 (To replace nickel-cadmium battery – Contact Adv. Pwr. for replacement details prior to battery purchase)	Advanced Power (877) 522-8837 (626) 969-7227	STC# SR00173SE	RG-380E/44	FAA-PMA Supplement No. 20, dd 11/13/95 and FAA TSO-C173
Bell	212 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Bell	214ST (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase) (Battery avail. through STC holder)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC# SR09225RC	RG-214	FAA-PMA Supplement No. 45, dd 10/22/02
Bell	222U (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC# SR09142RC	RG-380E/44	FAA-PMA Supplement No. 30, dd 05/18/97 and FAA TSO-C173
Bell	212, 412, 412EP (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC & STA# SR09053RC	RG-380E/44	FAA-PMA Supplement No. 23, dd 04/04/96 and FAA TSO-C173
Bell	206L-1, 206L-3, 206L-4 (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC & STA# SR09069RC	RG-222	FAA-PMA Supplement No. 25, dd 06/07/96 and FAA TSO-C173

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Bell	206L, 206L-1, 206L-3, 206L-4 (To replace nickel-cadmium battery – Contact Adv. Pwr. For replacement details prior to battery purchase)	Advanced Power (877) 522-8837 (626) 969-7227	STC# SR00462SE	RG-222	FAA-PMA Supplement No. 48, dd 12/02/02 and FAA TSO-C173
Bell	407 (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase) (Battery avail. through STC holder)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC# SR09359RC	RG-407A1	FAA-PMA Supplement No. 58, dd 06/19/03
Bell	407 (To replace nickel-cadmium battery – Contact Rotorcraft for replacement details prior to battery purchase)	Rotorcraft Support (818) 997-7667	STC# SR01456LA	RG-407	FAA-PMA Supplement No. 62, dd 10/30/03 and FAA TSO-C173
Boeing	737-600, -700, -800, -900 Series (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST03932AT (Kit)	RG-380E/60B 9507 (Dummy Temperature Plug)	FAA-PMA Supplement No. 96, dd 09/28/11 and P/N RG-380E/60B is FAA TSO-C173 authorized
Bombardier Inc.	BD-100-1A10 (Challenger 300) (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST01488WI (Kit)	RG-441 5-0123 (TS-C3 Temperature Sensor)	FAA-PMA Supplement No. 85, dd 01/07/09 & P/N RG-441 is FAA TSO-C173 authorized.
Bombardier Inc.	DHC-8-100, 8-200, 8-300, 8-400 Series (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST01643WI (Kit)	RG-380E/44 or RG-380E/60L Installation Kit: 5-0290 (-100, -200, -300 Series) Installation Kit: 5-0291 (-400 Series)	FAA-PMA Supplement No. 95, dd 09/09/11 & P/N RG-380E/44 and RG-380E/60L are FAA TSO-C173 authorized
British Aerospace	Jetstream 3101 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SA2994SO	RG-390E	FAA-PMA Supplement No. 16, dd 05/18/92 and FAA TSO-C173
British Aerospace	Jetstream 3201 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SA2995SO	RG-390E	FAA-PMA Supplement No. 16, dd 05/18/92 and FAA TSO-C173
British Aerospace	Jetstream 3201 (S/N: 790 – 9999) (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST00342LA	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 32, dd 06/11/97 and FAA TSO-C173
Cessna	150, 152, A/F/F/A 152, 172, 172A, P/R 172, 175, 188, 310, 310G/L, 320, 320D/E, 340	Concorde Battery (800) 757-0303	FAA Design Approval	CB-25	FAA-PMA Supplement No. 8, dd 03/03/88
Cessna	210 (S/N: 21059503 & on), T210	Wilco (800) 767-7593 (316) 943-9379	STC# SA2558CK	RG24-11M	FAA-PMA Supplement No. 14, dd 02/07/91
Cessna	182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R, R182/TR182, 182R/T182 (182 Series through S/N: 18265965 Except: 18263479)	Wilco (800) 767-7593 (316) 943-9379	STC# SA00753WI	CB-35A RG-35A RG-35AXC	FAA-PMA Supplement No. 41, dd 08/16/01 Amended: dd 08/13/02
Cessna	182 Series (S/N:18263479, 18265966 and up), R182 and TR182 Series (S/N: R18200001 and up)	Wilco (800) 767-7593 (316) 943-9379	STC# SA00753WI	RG24-15	FAA Supplement No. 41, dd 08/16/01 Amended: dd 08/13/02
Cessna	425 (Conquest I) (To replace nickel-cadmium battery – Contact Wilco for replacement details prior to battery purchase)	Wilco (800) 767-7593 (316) 943-9379	STC# SA2435CE	RG-380E/44	FAA-PMA Supplement No. 14, dd 02/07/91 and FAA TSO-C173
Cessna	425 (Conquest I) (To replace nickel-cadmium battery – Contact Wilco for replacement details prior to battery purchase)	Wilco (800) 767-7593 (316) 943-9379	STC# SA2436CE	CB24-380E	FAA-PMA Supplement No. 14, dd 02/07/91
Cessna	441 (Conquest II) (To replace nickel-cadmium battery – Contact Wilco for replacement details prior to battery purchase)	Wilco (800) 767-7593 (316) 943-9379	STC# SA2496CE	RG-380E/44	FAA-PMA Supplement No. 14, dd 02/07/91 and FAA TSO-C173
Cessna	441 (Conquest II) (To replace nickel-cadmium battery – Contact Wilco for replacement details prior to battery purchase)	Wilco (800) 767-7593 (316) 943-9379	STC# SA2247CE	CB24-380E	FAA-PMA Supplement No. 14, dd 02/07/91

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Cessna	<p align="center">SINGLE ENGINE MODELS</p> <p>120, 140, 140A, 150, 150A, 150B, 150C, 150D, 150E, 150F, 150G, 150H, 150J, 150K, 150L, 150M, A150K, A150L, A150M, 152, A152, 170, 170A, 170B, 172, 172A, 172B, 172C, 172D, 172E, 172F (USAF T-41A), 172G, 172H (USAF T-41A), 172I, 172K, 172L, 172M, 172N, 172P, 172Q, 172R, 172S, 175, 175A, 175B, 175C, P172D, R172E (USAF T-41B)(USAF T41C&D), R172F(USAF T-41D), R172G ((USAF T-41C & T-41D), R172H (USAF T-41D), R172J, R172K, 172RG, 177, 177A, 177B, 177RG,180, 180A, 180B, 180C, 180D, 180E, 180F, 180G, 180H, 180J, 180K, 182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R/T182, R182, TR182, 182S, 182T, T182T, 185, 185A, 185B, 185C, 185D, 185E, A185E, A185F, 188, 188A, A188, A188A, 188B, A188B, T188C, 190, 195, 195A, 195B, 206, 206H, U206, P206, U206A, P206A, P206B, TU206A, TU206B, TP206A, TP206B, U206B, P206C/TP206C, P206D/TP206D, P206E/TP206E, U206C/TU206C, U206D/TU206D, U206E/TU206E, U206F/TU206F, U206G/TU206G, T206H, 207/T207, 207A/T207A, 305B, 305E, 210, 210A, 210B, 210C, 210D, 210E, 210F, T210F, 210G, T210G, T210H, 210H, T210J, 210J, 210K/T210K, 210L/T210L, 210M/T210M, 210N, P210N, T210N, 210R, P210R, T210R, 210-5 (205), 210-5A (205A), 305B, 305E (Military TO-1D, O-1D, O-1F), 337, 337A (USAF O2B), 337B, 337C, 337D, 337E, 337F, 337G, 337H/T337H, T337B, T337C, T337D, T337E, T337F, T337G, M337B (USAF O2A), P337H, T337H-SP</p> <p align="center">TWIN ENGINE MODELS</p> <p>T303, 310, 310A (USAF U-3A), 310B, 310C, 310D, 310E (USAF U-3B), 310F, 310G, 310H, E310H, E310I, E310J, 310J, 310J-1, E310K, 310L, 310N, 310P, T310P, 310Q, T310Q, 310R, T310R, 320, 320-1, 320A, 320B, 320C, 320D, 320E, 320F, 335, 340, 340A, 401, 401A, 401B, 402, 402A, 402B, 402C, 404, 411, 411A, 414, 414A, 421, 421A, 421B, 421C</p>	Concorde Battery (800) 757-0303	STC# SA01118WI (See Note 3)	<p>CB-25 CB-25XC RG-25 RG-25XC Replaces original battery p/n 0511319-1</p> <p>CB-35A CB-35AXC RG-35A RG-35AXC Replaces original battery p/n 0712605-1 or 0712604-1 or 0311053</p> <p>CB-24-11 RG24-12 RG24-16 (P/N RG24-11 and RG24-15 are approved for installation, but are not recommended due to some fitment issues.) Replaces original battery p/n C614001-0106</p> <p>CB-24-11M RG-24-11M RG-24-15M Replaces original battery p/n C614002-0102</p> <p>RG24-10 (P/N RG24-9 is approved for installation, but not recommended due to some fitment issues) Replaces original battery p/n C614001-0105</p> <p>RG24-20 Replaces original battery p/n 5018200-201 & REBAT p/n R2425</p>	FAA-PMA Supplement No. 83, dd 9/20/07 Amended 10/21/09

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Cessna	120, 140, 140A, 170, 170A, 170B, 172 thru 172Q, 172R, 172S, 210, 210A thru 210R, T210F thru T210R, P210N, P210R, 210-5, 210-5A, 175, 175A, 175B, 175C, 172RG, P172D, R172E, R172F thru R172K, 177, 177A, 177B, 177RG, 180, 180A thru 180K, 185, 185A thru 185E, A185E, A185F, 188, 188A, 188B, A188, A188A, A188B, T188C, 206, U206, P206, U206A, P206A, P206B, TU206A, TU206B, TP206A, TP206B, U206B, P206C/TP206C thru P206E/TP206E, U206C/TU206C thru U206G/TU206G, 206H, 207, 207A, T207, T207A, 305B, 305E, 337, 337A thru 337H T337B thru T337H, M337B, P337H, T337H-SP, 150, 150A thru 150M, A150K thru A150M, 152, A152	Wilco (800) 767-7593 (316) 943-9379	STC# SA00897WI (See Note 3)	RG-25 or RG25XC Replaces original battery p/n 0511319-1 RG-35A or RG35AXC Replaces original battery p/n 0712605-1 RG24-11 RG24-15 Replaces original battery p/n C614002-0102 RG24-11M RG24-15M Replaces original battery p/n C614001-0106	FAA-PMA Supplement No. 43, dd 09/04/01
Cessna	550 (Citation II) Series (To replace standby nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST01639LA	RG-131	FAA TSO-C173
Cessna	(Caravan) 208, 208B (Replaces p/n RG-380E/44 or RG-380E/40B w/ two (2) RG-390E in conjunction with engine conversion)	Texas Turbine Conversions (972) 382-4402	STC# SA10841SC	RG-390E	FAA-PMA Supplement No. 89, dd 10/27/09 and FAA TSO-C173
Cessna	(Caravan) 208, (Citation II) 500, 501, 550, 551 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Cessna	(Caravan) 208, 425, 441, (Citation II) 500, 501, 550, 551 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Cirrus	SR20, SR22	Concorde Battery (800) 757-0303	STC# SA01304WI	CB24-11M, RG24-11M, RG24-15M	FAA-PMA Supplement No. 76, dd 02/18/05
Dassault	Falcon 10 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST00774LA (Kit)	RG-390E	FAA-PMA Supplement No. 39, dd 04/23/99 and FAA TSO-C173
Dassault	Falcon 20 Series, C, D, E, F (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Dassault	Falcon 20 Series, C, D, E, F (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Dassault	Falcon 50, 50EX, 900, 900EX, 900DX, 2000, 2000EX (Emergency battery replacement only to replace nickel-cadmium or lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST01571WI	RG-128 Series	FAA-PMA Supplement No. 90, dd 02/12/10 and FAA TSO-C173
Dassault	MF 50 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase) (Battery Mod. avail. through Dassault)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390E/LS	FAA-PMA Supplement No. 51, dd 02/21/03 and FAA TSO-C173
Dassault	Falcon MF900, F900EX To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase) (Battery Mod. avail. through Dassault)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390E/LS	FAA-PMA Supplement No. 51, dd 02/21/03 and FAA TSO-C173
Dassault	Falcon 2000 To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase) (Battery Mod. avail. through Dassault)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44LS	FAA-PMA Supplement No. 51, dd 02/21/03 and FAA TSO-C173

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
de Havilland Aircraft	See Bombardier Inc.				
Embraer	EMB-110P1, EMB-110P2 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Embraer	EMB-110P1, EMB-110P2 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Embraer	EMB-500 (To replace lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SA01633WI	RG-390E	FAA-PMA Supplement No. 94, dd 09/09/11 and FAA TSO-C173
Embraer	135BJ, 135ER, 135LR, 135KE, 135KL, 145, 145EP, 145ER, 145LR, 145MP 145MR, 145XR (To replace nickel-cadmium battery - Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST01520WI (Kit)	RG-442 (Battery) 5-0124 (TS-C4 Temperature Sensor)	FAA-PMA Supplement No. 86, dd 03/09/09 & P/N RG-442 is FAA TSO-C173 authorized.
Enstrom Helicopter	F-28F & 280FX	Enstrom Helicopter (906) 863-1200	TC# H1CE, Rev. 20, Rev. A	RG24-11M (24V) & RG-35A (12V)	FAA-PMA Supplement No. 23, dd 04/04/96
Erco / Ercoupe	(See Univair)				
Eurocopter	AS350 B, BA, B1, B2, B3, D (To replace p/n 151CH-1 nickel-cadmium battery as a substitute for p/n 1606-1 as covered on the American Eurocopter STC)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-350	FAA-PMA Supplement No. 52, dd 02/18/03 and FAA TSO-C173
Eurocopter	AS350 B, B1, B2, BA, C, D, D1 (To replace p/n 1606-1 nickel-cadmium battery)	Falcon Crest (800) 833-5422 (713) 644-2290	STC# SR09185RC	RG-355	FAA-PMA Supplement No. 35, dd 03/06/98 and FAA TSO-C173
Eurocopter	AS355 E, F, F1, F2, N (To replace p/n 1606-1 nickel-cadmium battery)	Falcon Crest (800) 833-5422 (713) 644-2290	STC# SR09186RC	RG-355	FAA-PMA Supplement No. 35, dd 03/06/98 and FAA TSO-C173
Eurocopter	BK-117-A-1, -A-3, -A-4, -B-1, -B-2, -C-1 (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase)	Falcon Crest (800) 833-5422 (713) 644-2290	STC & STA# SR09034RC	RG-390E	FAA-PMA Supplement No. 21, dd 11/15/95 and FAA TSO-C173
Eurocopter	BO-105C & BO-105S (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase)	Falcon Crest (800) 833-5422 (713) 644-2290	STC# SR09016RC	RG-390E	FAA-PMA Supplement No. 21, dd 11/15/95 and FAA TSO-C173
Eurocopter	EC130B4 (To replace p/n 151CH-1 nickel-cadmium battery – Contact Rotorcraft Support for details)	Rotorcraft Support (818) 997-7667	STC# SR02073LA	RG-350	FAA-PMA Supplement No. 88, dd 07/15/09 and FAA TSO-C173
Fairchild Aircraft	(See M-7 Aerospace)				
Garlick Helicopters	Bell UH-1F, UH-1P, TH-1F (To replace nickel-cadmium battery – Contact Tamarack for replacement details prior to battery purchase)	Tamarack Helicopters (406) 777-1044	(Omitted temporarily pending STC number correction)	RG-390E	FAA-PMA Supplement No. 53, dd 03/26/03 and FAA TSO-C173
Global Amphibians	(See Revo Inc.)				
Globe	GC-1A, GC-1B	Swift Museum Foundation (423) 745-9547	TC# A-766	RG-35A	FAA-PMA Supplement No. 63, dd 10/30/03
Grumman Aircraft	(See True Flight Holdings LLC)				
Gulfstream Aerospace	Galaxy/Gulfstream 200	Gulfstream Aerospace (214) 902-7770	STC# ST09945SC	5-0122	FAA-PMA Supplement No. 87, dd 04/13/09
Gulfstream Aerospace	Israel Aircraft Ind. Galaxy/Gulfstream 200 (To replace part no. 414377)	Gulfstream Aerospace (214) 902-7770	(Main battery obsolete – Contact Gulfstream for updated STC info.)	RG-380E/44C or RG-380E/60C	FAA-PMA Supplement No. 56, dd 05/27/03
Gulfstream Aerospace	Israel Aircraft Ind. Galaxy/Gulfstream 200 (To replace part no. 2778-18)	Gulfstream Aerospace (214) 902-7770	(Standby battery obsolete – Contact Gulfstream for updated STC info.)	RG-390E/C	FAA-PMA Supplement No. 56, dd 05/27/03

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Gulfstream Aerospace	Israel Aircraft Ind. Galaxy/Gulfstream 200 (Temperature Sensor)	Gulfstream Aerospace (214) 902-7770	(New temp sensor assy. – Contact Gulfstream for updated STC info.)	5-0054 (CBC Kit #TS-C2)	FAA-PMA Supplement No. 56, dd 05/27/03
Gulfstream Aerospace	(Gulfstream I) G-159 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Gulfstream Aerospace	GII (G-1159), GIII (G-1159A), GII (G-1159B) (DC System) (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST00773LA	RG-380E/44	FAA-PMA Supplement No. 40, dd 04/30/99 and FAA TSO-C173
Gulfstream Aerospace	GIII (G-1159A)(s/n 357, 402 & up), GIV (AC System) (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST00544LA (Kit)	RG-380E/44	FAA-PMA Supplement No. 38, dd 11/02/98 and FAA TSO-C173
Hawker Beechcraft	F33A, F33C, V35B, A36, A36TC	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-11	FAA-PMA Supplement No. 5, dd 05/18/82
Hawker Beechcraft	77	Concorde Battery (800) 757-0303	FAA Design Approval	CB-25	FAA-PMA Supplement No. 1, dd 03/03/81 Amended: dd 03/03/88
Hawker Beechcraft	MU-300-10, 400, 400A (To replace nickel-cadmium battery – Contact Hawker Beechcraft for replacement details prior to battery purchase)	Hawker Beechcraft (800) 256-6012 (404) 699-9228	STC# SA2494SO	RG-380E/40B	FAA-PMA Supplement No. 22, dd 01/23/96 and FAA TSO-C173
Hawker Beechcraft	A200CT (Military) RC-12K	Wilco (800) 767-7593 (316) 943-9379	FAA Design Approval	TS-C6 (Temperature Sensor selling p/n 5-0125)	FAA-PMA Supplement No. 70, dd 05/28/04
Hawker Beechcraft	Kingair 65-90, 65-A90, B90, C90, E90, F90, 99, A100, B100, 200, 300, MU-300- 10, 400, 400A, 400T, (T-1A) Concorde (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Hawker Beechcraft	Kingair 65-90, 65-A90, 65-A90-1 (JU-21A, U-21A, RU-21A, RG-21D, U-21G, RU- 21H), 65-A90-4 (RU-21E, RU-21H), B90, C90, 65-A90-2 (RU-21B), 65-A90-3 (RU- 21C), E90, H90 (T-44A), C90A, F90, 99, 99A, 99A (FACH), 100, A99, A99A, A100 (U-21F), B99, A100A, B100, C99, 200 (A100-1(U-21J)), A200C (UC- 12B), 200C, B200, B200C (C-12F, UC- 12F, UC-12M, C-12R), A200 (C-12A, C- 12C), 200T, 200CT, A200CT (C-12D, C- 12F, FWC-12D, RC-12D, RC-12F, RC- 12G, RC-12H, RC-12K, RC-12P, RC-12Q), B200CT, B200T, 300, 300LW, B300, B300C, 1900, 1900C, 1900C (C-12J), 1900D (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SA01260WI	RG-380E/40L RG-380E/40K RG-380E/44L RG-380E/44K RG-380E/60L RG-380E/60K	FAA-PMA Supplement No. 73, dd 08/11/04 and FAA TSO-C173
Hawker Beechcraft	Kingair 65-90, 65-A90, 65-A90-1 (Military U-21A, RU21A, RU21D, JU21A, U-21G, RU21H/GRV), 65-A90-4 (Military RU21E, RU21H/GRV & IV), B90, C90, 65-A90-2 (Military RU-21B), 65-A90-3 (Military RU- 21C), E90, H90, (Military T-44A), C90A, F90, 99 & 99A, (Military 99A), 100, A99, A99A, A100 (Military U-21F), B99, A100A, B100, C99, 200, A200C, (Military UC-12), 200C, B200, B200C, (Military C12F, UC- 12F & UC-12M), A200 (Military C-12A, C- 12C), 200T, 200CT, A200CT (Military C- 12D, FWC-12D, RC-12D, C-12F, RC-12G, RC-12H), B200CT, B200T, 200T, A100-1 (Military U-21J), A200CT (Military RC-12K), 1900, 1900C (Bladder Fuel), 1900C (Wet Wing), 1900C (Military C-12J), 1900D, 300, 300LW, B300, B300C, (S/N: FM-1 & subsequent, FN-1 & subsequent) (To replace nickel-cadmium battery – Contact Wilco for replacement details prior to battery purchase)	Wilco (800) 767-7593 (316) 943-9379	STC# SA00741WI	RG-380E/40K RG-380E/44K RG-380E/60K	FAA-PMA Supplement No. 41, dd 08/16/01 Amended: dd 08/13/02 and FAA TSO-C173
Hawker Beechcraft	65-90, 65-A90, B90, C90, E90, F90, 99, A100, B100, 200 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Hawker Beechcraft	200, 300, & B300 Series (To replace nickel-cadmium battery – Contact Hawker Beechcraft for replacement details prior to battery purchase)	Hawker Beechcraft (800) 256-6012 (404) 699-9228	STC# SA2699SO	RG-380E/40B	FAA-PMA Supplement No. 22, dd 01/23/96 and FAA TSO-C173
Hawker Beechcraft	BAe 125-800A (To replace lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SA2984SO	RG-390E	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Hawker Beechcraft	400A (S/N RK-98 and after) (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/40L	FAA-PMA Supplement No. 49, dd 1/23/03 and FAA TSO-C173
Hawker Beechcraft	Hawker 1000 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST00640LA (Kit)	RG-380E/60K	FAA-PMA Supplement No. 39, dd 04/23/99 and FAA TSO-C173
Hawker Beechcraft	BH.125 Series 1A, 1A/522, 1A/R-522, 1A/S-522; Series 3A, 3A/R, 3A/RA, BH.125 400A, 600A, HS.125 600A, 700A, BAe 125-800A; Hawker 800, 800XP (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST00415LA	RG-390E	FAA-PMA Supplement No. 39, dd 04/23/99 and FAA TSO-C173
Hawker Beechcraft	DH.125 Series, HS.125 Series, BH.125 Series (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase) (STC to replace emergency battery only)	Concorde Battery (800) 757-0303	STC# ST01223WI	RG-125	FAA-PMA Supplement No. 65, dd 01/30/04 and FAA TSO-C173
Hawker Beechcraft	400A Series (S/N's RK-98 and after) (To replace 38Ah lead-acid battery – Contact Hawker Beechcraft for replacement details prior to battery purchase)	Hawker Beechcraft (800) 256-6012 (404) 699-9228	STC# ST02506AT	RG-380E/44 RG-380E/44L RG-380E/60L	FAA-PMA Supplement No. 44, dd 06/13/02 and FAA TSO-C173
Hawker Beechcraft	35, A35, B35, C35, 35R, D35, E35, F35, G35, H35, J35, K35, M35, 35-33, N35, 35-A33, 35-B33, P35, S35, 35-C33, E-33, F-33, G-33, V35, V35A, V35B, 35-C33A, E33A, E33C, 36, A36, F33A, F33C, A36TC, B36TC, 23, A23, A23A, A23-19, A23-24, A24, 19A, M19A, B19, B23, C23, A24R, B24R, C24R	Wilco (800) 767-7593 (316) 943-9379	STC# SA00638WI	RG-35A RG-35AXC RG24-15 (P/N RG24-16 – See next entry for RG24-16 eligibility)	FAA-PMA Supplement No. 37, dd 06/22/98 Amended: dd 06/29/98
Hawker Beechcraft	C23, C24R, F33A, F33C, G33, V35B, A36, A36TC	Wilco (800) 767-7593 (316) 943-9379	STC# SA00638WI	RG24-16	FAA-PMA Supplement No. 82, dd 07/18/07
Israel Aircraft	(Jet Commander) 1121, 1121A, 1121B (Westwind) 1123, 1124 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Israel Aircraft	(Jet Commander) 1121, 1121A, 1121B (Westwind) 1123, 1124 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
JetProp LLC	Piper PA-46-310P, PA-46-350P	Rocket Eng. / Jet Prop LLC (509) 535-4401	STC# ST00541SE	RG-46	FAA-PMA Supplement No. 54, dd 04/29/03
JetProp LLC	Piper PA-46-310P, PA-46-350P (Higher Capacity Replacement)	Rocket Eng. / Jet Prop LLC (509) 535-4401	STC# ST00541SE	RG-49	FAA-PMA Supplement No. 54, dd 04/29/03 and FAA TSO-C173
Kaman Aerospace	K1200	Concorde Battery (800) 757-0303	TC# TR7BO	RG-380E/40B	FAA-PMA Supplement No. 26, dd 06/21/96 and FAA TSO-C173
Lake	(See Revo Inc.)				
Learjet	23, 24, 25, 28, 29, 35, 36 (To replace lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Learjet	23, 24, 25, 28, 29, 35, 36, 55 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Learjet	40, 45 (To replace Concorde part no. RG-443 – Contact the STC holder for replacement details prior to battery purchase) (STC for emergency battery only)	Global Aviation Tech. (316) 425-0998	STC# ST01639WI (Kit)	RG-145-2	FAA-PMA Supplement No. 93, dd 09/09/11 and FAA TSO-C173
Learjet	45 (To replace lead-acid emergency battery – Contact Concorde for replacement details prior to battery purchase) (STC for emergency battery only)	Concorde Battery (800) 757-0303	STC# ST01173WI	RG-443	FAA-PMA Supplement No. 59, dd 06/23/03
Learjet	55	Ni-Cad Systems (510) 785-9391	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 14, dd 02/07/91
M-7 Aerospace	Fairchild SA226-AT, SA227-AT, SA226-T, SA227-CC, -DC (RG-390ES replaces M-7 Aerospace p/n FASRG390ESTC)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390ES	FAA-PMA Supplement No. 60, dd 06/25/03 and FAA TSO-C173
M-7 Aerospace	Fairchild SA227AC, SA227BC (RG-390ES replaces M-7 Aerospace p/n FASRG390ESTC)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390ES	FAA-PMA Supplement No. 17, dd 06/27/95 and FAA TSO-C173
M-7 Aerospace	Fairchild SA226-T, SA226-T(B), SA227-TT (To replace p/n RG-91A which replaces M-7 Aerospace p/n FASRG91STC)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-91	FAA-PMA Supplement No. 69, dd 05/17/04
Maule Aerospace Technology Inc.	M-4-210, M-4-220, M-4-180, M-5-180, M-5-210, M-5-220, M-5-235, M-5-210TC, M-5-200, M-6-180, M-6-235, M-7-235, M-7-235A, M-7-235B, M-7-235C, M-7-260, M-7-260C, M-8-235, MT-7-235, MT-7-260, MX-7-160, MX-7-160C, MX-7-180, MX-7-180A, MX-7-180B, MX-7-180C, MX-7-180AC, MX-7-235, MXT-7-160, MXT-7-180, MXT-7-180A	Maule Aerospace (229) 985-2045	FAA Design Approval	RG-35A RG-35AXC	FAA-PMA Supplement No. 64, dd 01/06/04
MD Helicopter	MD369, 369A, 369D, 369F, 369FF, 369H, 369HM, 369HS, 369HE, 369E and 500N (To replace nickel-cadmium battery – Contact Adv. Pwr. For replacement details prior to battery purchase)	Advanced Power (877) 522-8837 (626) 969-7227	STC# SR00716SE (Kit)	RG-500 CBP-3349-2W (Connector – Selling p/n 4002) 9542 (Adaptor)	FAA-PMA Supplement No. 47, dd 12/02/02 & P/N RG-380E/44 is FAA TSO-C173 authorized
MD Helicopter	600N (To replace nickel-cadmium battery with the connector receptacle on right side of battery container – Used for most 600N models)	Concorde Battery (800) 757-0303	STC# SR01564LA (Kit)	RG-600-1 CBP-3349-2W (Connector – Selling p/n 4002) 9542 (Adaptor)	FAA-PMA Supplement No. 67, dd 02/06/04 & P/N RG-380E/44 is FAA TSO-C173 authorized
MD Helicopter	600N (To replace nickel-cadmium battery with the connector receptacle on left side of battery container)	Concorde Battery (800) 757-0303	STC# SR01564LA	RG-600-2 CBP-3349-2W (Connector – Selling p/n 4002) 9542 (Adaptor)	FAA-PMA Supplement No. 67, dd 02/06/04 & P/N RG-380E/44 is FAA TSO-C173 authorized
MD Helicopter	MD-900 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SR03895AT (Kit)	RG-407 Elbow Coupling Assy #5-0349 (Assy includes #8003, Elbow, vent adaptor, and Coupling #8086)	FAA PMA Supplement No. 92, dd 09/09/11 & P/N RG-407 is FAA TSO-C173 authorized.
Mitsubishi	MU-2B, MU-2B-10, -15, -20, -25, -26, -26A, 30, 35, 36, 36A, 40, 60, MU-300-1, -1A (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Mitsubishi	YS-11A Series (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SA2795SO	RG-390E	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Mooney	M20 (w/ R-33 or R-35 battery), M20A (w/ R-33 or R-35 battery), M20B, -20C, -20D, -20E, -20F, M20G, M20J (S/N 24-0001 to 24-2999), M20K (S/N 25-0001 to 25-0999)	Concorde Battery (800) 757-0303	Identity per 14 CFR § 21.303	RG-35A (To replace R-33) or RG-35AXC (To replace R-35)	FAA-PMA Supplement No. 77, dd 03/01/05

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Mooney	M20J, M20K	STC/Mooney Ltd. (830) 792-2918	STC# SA00081SE & STC# SA5691NM	RG-35A	FAA-PMA Supplement No. 24, dd 05/06/96
Mooney	M20J, M20K, M20L, M20M, M20R, M20S, M20TN (24V models)	Concorde Battery (800) 757-0303	Identity per 14 CFR § 21.303	RG24-11M (to replace manifold vented battery) or RG24-15	FAA-PMA Supplement No. 84, dd 02/01/08
Piaggio Aero Industries SpA	P180	Concorde Battery (800) 757-0303	STC# SA01653LA (Kit)	RG-380E/40L (Battery) TS-C6A (Temperature Sensor selling p/n 5-0242)	FAA-PMA Supplement No. 74, dd 09/27/04 and FAA TSO-C173 (TSO for P/N RG- 380E/40L only)
Pilatus Britten Norman Ltd.	(See B-N Group Ltd.)				
Pilatus	PC-12 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST00776LA	RG-380E/44	FAA-PMA Supplement No. 39, dd 04/30/99 and FAA TSO-C173
Piper	PA-12, PA-12S, PA-18, PA-18 "105" (Special), PA-18 "125" (Army L-21B), PA-18 "135" (Army L-21B), PA-18 "150", PA-18A, PA-18A "135", PA-18A "150", PA-18S, PA-18S "105", PA-18S "125", PA- 18S "135", PA-18S "150", PA-18AS "125", PA-18AS "135", PA-19 (Army L-18C), PA-19S, PA-20, PA- 20 "115", PA-20 "135", PA-20S, PA-20S "115", PA-20S "135", PA-22, PA-22-108, PA-22-135, PA-22-150, PA-22-160, PA-22S-135, PA-22S-150, PA-22S-160, PA-23, PA-23-160, PA-23-235, PA-23-250 (Navy UO-1), PA-E23-250, PA-24, PA-24-250, PA-24-260, PA-25, PA-25-235, PA-25-260, PA-28-140, PA-28-150, PA-28-151, PA-28-160, PA-28-161, PA-28-180, PA-28-181, PA-28-201T, PA-28-235, PA-28-236, PA-28R-180, PA-28R-200, PA-28R-201, PA-28R-201T, PA-28RT-201, PA-28RT-201T, PA-28S-160, PA-30, PA-31, PA-31-300, PA-31-350 & T-1020, PA-31-325 C/R, PA-32-260, PA-32-300, PA-32-301, PA-32-301T, PA-32S-300, PA-32R-300, PA-32RT-300, PA-32RT-300T, PA-32R-301, PA-32R-301T, PA-34-200, PA-34-200T, PA-34-220T, PA-36-285, PA-36-300, PA-36-375, PA-36-285, PA-38-112, PA-39, PA-40, PA-44-180, PA- 44-180T TURBO, PA-46-310P, PA-46-350P, PA-60-600, PA- 60-601, PA-60-601P, PA-60-602P, PA-60-700P, PA-400	Concorde Battery (800) 757-0303	STC# SA01147WI (See Note 3)	CB-25 CB-25XC RG-25 RG-25XC Replaces original battery p/n 450- 030 RG-25 Replaces original battery p/n 450- 022 CB-35A CB-35AXC RG-35A RG-35AXC Replaces original battery p/n 450- 035 (Please note a replacement battery box cover may be required for the RG series—Contact CBC) CB24-11 RG24-11 RG24-15 Replaces original battery p/n 450- 027 or 450-032 CB24-11M RG24-11M RG24-15M Replaces original battery p/n 450- 101 RG24-20 Replaces original battery p/n 450- 028, 450-031 or 450-029 (Please note an installation kit may be required – Contact CBC)	FAA-PMA Supplement No. 50, dd 3/7/03

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Piper	PA-12, PA-12S PA-18, PA-19 (Army L-18C), PA-18 "125" (Army L-18A) , PA-18 "135" (Army L-21B), PA-18A, PA-18A "135", PA-18 « 105 », PA-18S, PA-19S, PA-18S "125", PA-18S "135", PA-18AS "125", PA-18AS "135", PA-18S "105", PA-18 "150", PA-18A "150", PA-18S "150", PA-18A, PA-18A "135", PA-18A "150" PA-20, PA-20 "115", PA-20S, PA-20S "115", PA-20S "135", PA-20 "135", PA-22, PA-22-135, PA-22S-135, PA-22-150, PA-22S-150, PA-22-160, PA-22S-160, PA- 22-108, PA-24, PA-24-250, PA-24-400, PA-24-260, PA-25, PA-25-235, PA-25-260, PA-23, PA-23, PA-23-160, PA-23-250 (Navy UO-1), PA-28-160, PA-28-150, PA-28-180, PA-28S-160, PA-28S-180, PA- 28-235, PA-28-140, PA-28R-200, PA-28-151, PA-28-181, PA-28-161, PA-28R-201, PA-28R-201T, PA-28-236, PA-28RT-201, PA-28RT-201T, PA-28-201T, PA-32-260, PA-32-300, PA-32S-300, PA-32R-300, PA-32RT-300, PA-32RT-300T, PA-32R-301 (SP), PA-32R-301 (HP), PA-32R-301T, PA-32-301, PA-32-301T, PA-38-112, PA-36-285, PA-36-300, PA-36-375, PA-46-310P, PA-46-350P	Wilco (800) 767-7593 (316) 943-9379	STC# SA00954WI (See Note 3)	RG-25 or RG-25XC Replaces original battery p/n 450-030 RG-35A or RG-35AXC Replaces original battery p/n 450-035 RG24-11 or RG24-15 Replaces original Battery p/n 450-032 RG24-11M or RG24-15M Replaces original battery p/n 450-101 RG24-20 Replaces original battery p/n 450-031	FAA-PMA Supplement No. 43, dd 09/04/01
Piper	PA-23 Apache, PA-23-160, PA-23-250 (Navy UO-1), PA-23-235, PA-E-23-250 Aztec, PA-23-250, PA-31 Navajo, PA-31- 300 Navajo, PA-31-350 Chieftan & T-1020, PA-31-325 Navajo C/R, PA-44-180 Seminole, PA-44-180T Turbo Seminole, PA-30 Twin Comanche, PA-39 Twin Comanche, PA-40 Twin Comanche, PA- 34-200 Seneca, PA-34-200T Seneca II, PA-34-220T Seneca III, IV, V	Wilco (800) 767-7593 (316) 943-9379	STC# SA00954WI (See Note 3)	RG-25 or RG-25XC Replaces p/n 450-030 RG-35A or RG-35AXC Replaces p/n 450-035 RG24-11 or RG24-15 Replaces p/n 450-032 RG24-11M or RG24-15M Replaces p/n 450-101 RG24-20 Replaces p/n 450-031	FAA-PMA Supplement No. 61, dd 07/14/03
Piper	(Cheyenne) PA-31T, PA-31T1, PA-31T2, PA-31T3, PA-42, PA-42-720, PA-42-1000 (To replace nickel-cadmium battery – Contact Wilco for replacement details prior to battery purchase)	Wilco (800) 767-7593 (316) 943-9379	STC# SA00843WI	RG-380E/44L RG-380E/44K RG-380E/60L RG-380E/60K	FAA-PMA Supplement No. 80, dd 12/02/05 and FAA TSO-C173
Pitts	(See Aviat)				
Raytheon	(See Hawker Beechcraft)				
Revo Inc.	(Lake) LA-4, LA-4-200, Model 250 (S/N: 1-25 only)	Revo Inc. (Phone unknown)	FAA Design Approval	RG-35A or RG-35AXC	FAA-PMA Supplement No. 25, dd 06/07/96
Robinson Helicopter	R-22	Robinson Helicopter (310) 539-0508	TC# H10WE	RG-25XC	FAA-PMA Supplement No. 75, dd 02/18/05
Robinson Helicopter	R-44	Robinson Helicopter (310) 539-0508	TC# H11MN	RG-25XC (12V), RG24-15 (24V)	FAA-PMA Supplement No. 75, dd 02/18/05
Sabreliner	NA 265, NA 265-20, -30, -40, -70, -80 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Sabreliner	NA 265, NA 265-20, -30, -40, -70, -80 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Sabreliner	265-40, -60, -65, -70, -80 (To replace nickel-cadmium battery – Contact Jet Harbor for replacement details prior to battery purchase)	Jet Harbor Inc. (954) 772-2863	STC# ST01294AT	RG-380E/44	FAA-PMA Supplement No. 36, dd 04/20/98 and FAA TSO-C173
Sabreliner	265-65 (To replace nickel-cadmium battery – Contact Jet Harbor for replacement details prior to battery purchase)	Jet Harbor Inc. (954) 772-2863	STC# ST01294AT	RG-206	FAA-PMA Supplement No. 36, dd 04/20/98 and FAA TSO-C173
Short Brothers & Harland Ltd.	SD 3-30 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44	FAA-PMA Supplement No. 29, dd 01/17/97 and FAA TSO-C173
Short Brothers & Harland Ltd.	SD 3-30 (To replace emergency nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-126	FAA-PMA Supplement No. 29, dd 01/17/97 and FAA TSO-C173
Short Brothers & Harland Ltd.	SD 3-60 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44	FAA-PMA Supplement No. 28, dd 01/17/97 Amended: dd 02/21/97 and FAA TSO-C173
Short Brothers & Harland Ltd.	SD 3-60 (To replace emergency nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-126	FAA-PMA Supplement No. 28, dd 01/17/97 Amended: dd 02/21/97 and FAA TSO-C173
Sikorsky	CH-54B	Helicopter Transport (541) 754-2400	STC# SR01241SE	RG-390E	FAA-PMA Supplement No. 78, dd 3/2/05 and FAA TSO-C173
Sikorsky	S-76A (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SR00091LA	RG-380E/40B	FAA-PMA Supplement No. 19, dd 08/24/95 and FAA TSO-C173
Sikorsky	S-76B (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase) (Two each RG-390E Req.)	Concorde Battery (800) 757-0303	STC# SR03819AT	RG-390E	FAA-PMA Supplement No. 91, dd 04/09/10 and FAA TSO-C173
Sikorsky	S-76A, C, C+ (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase)	Falcon Crest Av. (800) 833-5422 (713) 644-2292	STC & STA# SR09050RC	RG-380E/44	FAA-PMA Supplement No. 22, dd 01/23/96 and FAA TSO-C173
Slingsby Aviation	Firefly Models T67M260 & T67M260-T3A	Slingsby Aviation (011) (44) (1751) 432474	TC# A73EU Rev. 2 BA 17, Issue 6	RG24-11M	FAA-PMA Supplement No. 27, dd 07/03/96
Socata	TBM 700 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SA00775LA	RG-380E/44	FAA-PMA Supplement No. 39, dd 04/23/99 and FAA TSO-C173
Stinson	(See Univair)				
Tamarack Helicopters	Bell UH-1F, TH-1F, UH-1P (To replace nickel-cadmium battery – Contact Tamarack for replacement details prior to battery purchase)	Tamarack Helicopters (406) 777-0144	STC# SR01349LA	RG-390E	FAA-PMA Supplement No. 53, dd 03/26/03 and FAA TSO-C173
Tiger Aircraft	(See True Flight Holdings LLC)				
True Flight Holdings LLC	AA-1, AA-1A, AA-1B, AA-1C, AA-5, AA-5A, AA-5B, AG-5B	Concorde Battery (800) 757-0303	STC# SA01250WI	CB-25 CB-25XC RG-25 RG-25XC RG24-11M RG24-15M	FAA-PMA Supplement No. 71, dd 06/04/04
Twin Commander	680T, 680V, 680W, 690, 690A, 690B, 690C, 695, 695A, 690D & 695B	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Twin Commander	680T, 680V, 680W, 690, 690A, 690B, 690C, 695, 695A, 690D & 695B	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44	FAA-PMA Supplement No. 15, dd 01/06/91 and FAA TSO-C173
Univair (Erco)	415-C, 415-D, 415-CD (S/N 113 and up)	Univair (303) 375-8882	TC# A-718 Rev. 29, dd 07/14/05	CB-25 or RG-25	FAA-PMA Supplement No. 79, dd 11/23/05
Univair (Erco)	Ercoupe: 415-E, 415-G, 415F-1 (All S/N's) Forney: F-1A (S/N 5715 – 5729)	Univair (303) 375-8882	TC# A-787 Rev. 33, dd 07/14/05	CB-25 or RG-25	FAA-PMA Supplement No. 79, dd 11/23/05
Univair (Erco)	Forney: F-1A (S/N 5730 and up) Alon: A-2, A-2A (All S/N) Mooney M-10 (All S/N)	Univair (303) 375-8882	TC# A-787 Rev. 33, dd 07/14/05	RG-25	FAA-PMA Supplement No. 79, dd 11/23/05
Univair (Stinson)	Stinson: 108, 108-1, 108-2, 108-3, 108-5	Univair (303) 375-8882	TC# A-767 Rev. 27, dd 07/14/05	CB-35A or RG-35A	FAA-PMA Supplement No. 79, dd 11/23/05

Approval per FAA TSO-C173

(See note 4)

CBC Battery Part number	Holder	Date of Approval
RG-42 and RG-42[]	Concorde Battery (800) 757-0303	May 27, 2011
RG-47 and RG-47[]	Concorde Battery (800) 757-0303	July 1, 2010
RG-49 and RG-49[]	Concorde Battery (800) 757-0303	July 1, 2010
RG-121 Series	Concorde Battery (800) 757-0303	December 3, 2007
RG-122 Series	Concorde Battery (800) 757-0303	December 3, 2007
RG-125	Concorde Battery (800) 757-0303	July 31, 2008
RG-126	Concorde Battery (800) 757-0303	July 31, 2008
RG-128 Series	Concorde Battery (800) 757-0303	June 25, 2008
RG-129 Series	Concorde Battery (800) 757-0303	June 25, 2008
RG-131	Concorde Battery (800) 757-0303	January 3, 2008
RG-132	Concorde Battery (800) 757-0303	June 25, 2008
RG-145-1 and RG-145-1[]	Concorde Battery (800) 757-0303	November 5, 2010
RG-145-2 and RG-145-2[]	Concorde Battery (800) 757-0303	November 5, 2010
RG-150-1	Concorde Battery (800) 757-0303	January 8, 2008
RG-150-2	Concorde Battery (800) 757-0303	January 8, 2008
RG-206 and RG-206[]	Concorde Battery (800) 757-0303	July 1, 2010
RG-222 and RG-222[]	Concorde Battery (800) 757-0303	March 27, 2009
RG-223 and RG-223[]	Concorde Battery (800) 757-0303	May 27, 2011
RG-224 and RG-224[]	Concorde Battery (800) 757-0303	May 27, 2011
RG-322 and RG-322[]	Concorde Battery (800) 757-0303	March 29, 2011
RG-350 and RG-350[]	Concorde Battery (800) 757-0303	July 1, 2010
RG-355 and RG-355[]	Concorde Battery (800) 757-0303	July 1, 2010
RG-380E/40B and RG-380E/40B[]	Concorde Battery (800) 757-0303	September 9, 2008
RG-380E/40L and RG-380E/40L[]	Concorde Battery (800) 757-0303	September 9, 2008
RG-380E/40LS and RG-380E/40LS[]	Concorde Battery (800) 757-0303	September 9, 2008
RG-380E/40K and RG-380E/40K[]	Concorde Battery (800) 757-0303	September 9, 2008
RG-380E/40KS and RG-380E/40KS[]	Concorde Battery (800) 757-0303	September 9, 2008
RG-380E/44 and RG-380E/44[]	Concorde Battery (800) 757-0303	August 15, 2008
RG-380E/44L and RG-380E/44L[]	Concorde Battery (800) 757-0303	August 15, 2008
RG-380E/44LS and RG-380E/44LS[]	Concorde Battery (800) 757-0303	August 15, 2008
RG-380E/44K and RG-380E/44K[]	Concorde Battery (800) 757-0303	August 15, 2008
RG-380E/44KS and RG-380E/44KS[]	Concorde Battery (800) 757-0303	August 15, 2008
RG-380E/60B and RG-380E/60B[]	Concorde Battery (800) 757-0303	November 4, 2010
RG-380E/60L and RG-380E/60L[]	Concorde Battery (800) 757-0303	July 29, 2009
RG-380E/60LS and RG-380E/60LS[]	Concorde Battery (800) 757-0303	July 29, 2009
RG-380E/60K and RG-380E/60K[]	Concorde Battery (800) 757-0303	July 29, 2009
RG-380E/60KS and RG-380E/60KS[]	Concorde Battery (800) 757-0303	July 29, 2009

CBC Battery Part number	Holder	Date of Approval
RG-390E and RG-390E[]	Concorde Battery (800) 757-0303	October 20, 2008
RG-390ES and RG-390ES[]	Concorde Battery (800) 757-0303	October 20, 2008
RG-390E/L and RG-390E/L[]	Concorde Battery (800) 757-0303	October 20, 2008
RG-390E/LS and R-390E/LS[]	Concorde Battery (800) 757-0303	October 20, 2008
RG-400E/13	Concorde Battery (800) 757-0303	March 6, 2008
RG-407 and RG-407[]	Concorde Battery (800) 757-0303	March 29, 2011
RG-441 and RG-441[]	Concorde Battery (800) 757-0303	November 7, 2008
RG-442 and RG-442[]	Concorde Battery (800) 757-0303	November 7, 2008
RG-500 and RG-500[]	Concorde Battery (800) 757-0303	July 1, 2010
RG-600 and RG-600[]	Concorde Battery (800) 757-0303	July 1, 2010
RG-1835-1 and RG-1835-2	Concorde Battery (800) 757-0303	February 19, 2009

NOTES

Note 1 - Installations listed may require the battery purchase of an STC and/or STC Kit, aircraft modifications, etc. Contact the Concorde factory or the Certificate Holder for installation replacement details prior to battery purchase.

Note 2 - The products listed herein may be subject to export restrictions imposed by the United States. Export Licenses may be required. Customers are advised to contact Concorde for additional information on ECCN or USML information as it pertains to these products.

Note 3 - It is highly recommended for the aircraft's original battery part number to be confirmed prior to choosing a replacement battery listed on this STC. The original number should be carefully matched to the Concorde battery listed as the replacement to avoid an error in battery selection. Please note for some replacement model numbers, there are certain Concorde models that are preferred based on fitment. Other batteries listed are for PMA information only. The original battery part number is typically available in the aircraft parts catalog.

Note 4 - The batteries listed under TSO were approved under Technical Standard Order C173 by the US Federal Aviation Administration which applies to permanently installed, rechargeable lead-acid batteries intended to provide power for aircraft equipment including emergency and standby systems and electrical power to start aircraft engines or auxiliary power units when required. Those installing a battery listed, on or in a specific type or class of aircraft, must determine that the aircraft installation conditions are within the TSO Standards. TSO articles must have a separate approval for installation in an aircraft. This article may be installed only according to 14 CFR part 43 or the applicable airworthiness requirements.